

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Etios/--

VIN: MJB29BT300101377

Odometer Reading: 282091

License Plate: KF28RDGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V11.30

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	2
ABS/VSC/TRC	3
Cruise control	0
Immobilizer	0
EMPS	0

DTC (5)

Engine and ECT (2 DTCs)

DTC	Description	Status
P1604	Startability fault	Current
P1604	Startability fault	History

ABS/VSC/TRC (3 DTCs)

DTC	Description	Status
C0215	Left rear speed sensor circuit	Current
C0273	ABS motor relay circuit open	Current
C1241	Low or high power supply voltage	Current

Technician Notes

2016941329

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.