Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261116104423
Test Time: 2026-11-16 10:44:23
Technician: Barney

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Etios/--
VIN: MBJB29BT600129092

Odometer Reading: 206686
License Plate: KZ97WJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.90

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
Engine and ECT	2
ABS/VSC/TRC	1
Cruise control ADAS	0
Immobilizer	0
EMPS	0

DTC (3)

Engine and ECT (2 DTCs)

DTC	Description	Status
P1604	Startability fault	Current
P1604	Startability fault	History

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	History

Technician Notes

2017325956

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.