



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240221101633
Test Time: 2024-02-21 10:16:33
Technician: Werner

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Almera/--
VIN: MDHBBAN17Z0731331

Odometer Reading: 83756.00km
License Plate: JS73PCGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.50

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine	 0
Transmission	 0
ABS	 0
Air bag	 0
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 1
BCM	 3
IPDM E/R	 0

DTC (4)

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
C1601	Battery VOLT	Past

BCM (3 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past
B2190	NATS antenna AMP	Past
B2193	Chain OF BCM-ECM	Past



Technician Notes

2016276051

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.