



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250701110102
Test Time: 2025-07-01 11:01:02
Technician: Werner

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Almera/--
VIN: MDHBBAN17Z0733091

Odometer Reading: 67553km
License Plate: LT37VJGP

Customer Information

Name: Dekra MFC AUCTION HOUSE


Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine	 1
Transmission	 1
ABS	 1
Air bag	 0
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 0
BCM	 3
IPDM E/R	 1

DTC (7)

Engine (1 DTC)

DTC	Description	Status
P1614	Chain of IMMU-Key	1 time

Transmission (1 DTC)

DTC	Description	Status
U0100	Loss of communication (ECM) A	Past

ABS (1 DTC)

DTC	Description	Status
U1002	System communication (CAN)	Past

BCM (3 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past



B2190	NATS antenna AMP	Past
B2193	Chain of BCM-ECM	Past

IPDM E/R (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Technician Notes

2016931175

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.