



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250429155420
Test Time: 2025-04-29 15:54:20
Technician: Andrick

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/March/Micra/--
VIN: MDHFBUK13Z0310059

Odometer Reading: 164529km
License Plate: JT26KTGP

Customer Information

Name: Dekra MFC AUCTION HOUSE








Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.10

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine	 0
ABS	 0
Air bag	 0
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 1
BCM	 4
IPDM E/R	 0

DTC (5)

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
C1601	Battery VOLT	Past

BCM (4 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past
B2190	NATS antenna AMP	Past
B2191	Difference OF key	Past
B2193	Chain OF BCM-ECM	Past

Technician Notes

201685924



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.