

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Datsun GO/--

VIN: MDHZBAAD0Z0502158

Odometer Reading: 67031km

License Plate: CX62870

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V9.50

Repair Order Number: --

System Scanned(6)

System	Status/DTC
Engine	 1
Air bag	 1
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 1
BCM	 3
IPDM E/R	 0

DTC (6)

Engine (1 DTC)

DTC	Description	Status
P0607	ECM	1 time

Air bag (1 DTC)

DTC	Description	Status
B142A:16	Ignition voltage	Past

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
C1608	Control unit	Past

BCM (3 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past
B2190	NATS antenna AMP	Past
B2193	Chain OF BCM-ECM	Past

Technician Notes
2016400506

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.