

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Datsun Go/--

VIN: MDHZBAAD0Z0519290

Odometer Reading: 56122km

License Plate: KHN006MP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V10.20

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine	 1
ABS	 3
Air bag	 1
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 2
BCM	 0
IPDM E/R	 0

DTC (7)

Engine (1 DTC)

DTC	Description	Status
P0607	ECM	Current

ABS (3 DTCs)

DTC	Description	Status
C1109	Battery voltage (abnormal)	Past
C1130	Engine signal 1	Past
U1002	System communication (CAN)	Past

Air bag (1 DTC)

DTC	Description	Status
B142A:16	Ignition voltage	Past

Electric Power Steering (EPS)/DAST 3 (2 DTCs)

DTC	Description	Status
C1601	Battery VOLT	Past
C1608	Control unit	Past

Technician Notes
2016903310

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.