



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250630143252
Test Time: 2025-06-30 14:32:52
Technician: Travino

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEEHBC00800076404
Odometer Reading: 63824
License Plate: KX93CMGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V14.10
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Injection	✓ 0
ABS	✗ 1
Airbag / pretensioners	✓ 0
Instrument panel	✓ 0
UCH	✓ 0
Variable PAS	✓ 0
Central gateway	✓ 0
Radio	✓ 0

DTC (1)

ABS (1 DTC)

DTC	Description	Status
DTC403713	Rear left hand wheel speed sensor circuit Open circuit	Active

Technician Notes

2016930947

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.