



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231214093306
Test Time: 2023-12-14 09:33:06
Technician: Travino

Mazda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mazda/Ranger / Mazda B-Series / Troller/--
VIN: MM6UR0YD1L0017661

Odometer Reading: 191139
License Plate: FJK005L

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V8.20

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(10)

System		Status/DTC
PCM (Powertrain Control Module)		 2
ABS (Anti-lock Brake System)		 0
RCM (Restraint Control Module)		 0
IPC (Instrument Panel Control Module)		 2
BCMii (Body Control Module)		 0
FCDIM (Front Control/Display Interface Module)		 1
HVAC (Heating Ventilation Air Conditioning)		 0
PAM (Parking Aid Module)		 0
SRM (Speech Recognition Module)		 0
TRM (Trailer Module)		 0

DTC (5)

PCM (Powertrain Control Module) (2 DTCs)

DTC	Description	Status
P064C:00-28	Glow Plug Control Module 1	CMDTCs
P0671:00-2F	Cylinder 1 Glow Plug Circuit / Open	CMDTCs

IPC (Instrument Panel Control Module) (2 DTCs)

DTC	Description	Status
U0257:00-28	Lost Communication With Front Controls / Display Interface Module	CMDTCs
U0263:00-28	Lost Communication With Speech Recognition Module	CMDTCs



FCDIM (Front Control/Display Interface Module) (1 DTC)

DTC	Description	Status
B10BD:13-0F	Multifunctional Switch	CMDTCs

Technician Notes

2016201503

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.