



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20241105095744
Test Time: 2024-11-05 09:57:44
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Sentra/--
VIN: MNTBBAB17Z0010859
Odometer Reading: 335811km
License Plate: CS47JJGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.00
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine	 0
ABS	 3
Air bag	 9
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 1
BCM	 4
IPDM E/R	 0

DTC (17)

ABS (3 DTCs)

DTC	Description	Status
C1109	Battery voltage (abnormal)	Past
C1103	Right front sensor 1	Current
C1115	ABS sensor (abnormal signal)	Past

Air bag (9 DTCs)

DTC	Description	Status
B1421:00	Frontal collision	Current
B1422:00	Side collision	Current
B0001:13	Driver airbag module [open]	Current
B0010:13	Assist A/B module [open]	Current
B1430:13	PRE-TEN front LH [open]	Current



B1431:13	PRE-TEN front RH [open]	Current
B1433:13	Right front pretensioner 2 [open]	Current
B0028:13	Side A/B module (right) [open]	Current
B0029:13	Right curtain A/B module [open]	Current

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
U1000	CAN COMM circuit	Past

BCM (4 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past
B2190	NATS antenna AMP	Past
B2191	Difference OF key	Past
B2193	Chain OF BCM-ECM	Past

Technician Notes

2016598816

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.