



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250828134254  
Test Time: 2025-08-28 13:42:54  
Technician: Sbu

# Nissan VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Nissan/Qashqai/--  
VIN: SJNFEAJ11Z2688108

Odometer Reading: 119908km  
License Plate: KHP213NW

## Customer Information

Name: Dekra MFC AUCTION HOUSE
















Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V10.30

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned ( 13 )

| System                               | Status/DTC  |
|--------------------------------------|---|
| Engine                               |  8   |
| ABS                                  |  2   |
| Air bag                              |  1   |
| Meter/M&A                            |  0   |
| Electric Power Steering (EPS)/DAST 3 |  0   |
| Air pressure monitor                 |  0   |
| HVAC                                 |  0   |
| EHS/PKB                              |   6 |
| IPDM E/R                             |  1   |
| BCM                                  |  3   |
| CAN gateway                          |  0   |
| Chassis control                      |   0 |
| 3-channel CAN gateway                |  0   |

## DTC ( 21 )

### Engine ( 8 DTCs )

| DTC      | Description                            | Status  |
|----------|--|---------|
| U0121:87 | Lost communication (abs)               | Past    |
| P2263:22 | Turbocharger/supercharger boost system | Current |
| P0560:16 | Battery voltage                        | Past    |
| P0141:13 | Oxygen sensor 2 heater (bank 1)        | Past    |



|          |                                 |      |
|----------|---------------------------------|------|
| P0135:13 | Oxygen sensor 1 heater (bank 1) | Past |
| P0014:77 | Camshaft position actuator B b1 | Past |
| P0597:13 | Thermostat                      | Past |
| P062C:64 | Control module                  | Past |

**ABS ( 2 DTCs )**

| DTC      | Description                | Status |
|----------|----------------------------|--------|
| C1130:92 | Engine signal 1            | Crnt   |
| C1109:16 | Battery voltage (abnormal) | Past   |

**Air bag ( 1 DTC )**

| DTC      | Description            | Status |
|----------|------------------------|--------|
| B142A:16 | Ignition voltage (Low) | Past   |

**EHS/PKB ( 6 DTCs )**

| DTC   | Description   | Status |
|-------|---|--------|
| C1BD4 | G sensor (Internal electric fault)                    | Past   |
| C10C8 | Control module (System internal fault)                | Past   |
| C1BD5 | Power supply voltage (Battery voltage low)            | Past   |
| C1BD5 | Power supply voltage (Circuit voltage out of range)   | Past   |
| C1BD7 | Clutch sensor Open circuit or short circuit to ground | Past   |
| C1BD5 | Power supply voltage (Event information)              | Past   |

**IPDM E/R ( 1 DTC )**

| DTC   | Description  | Status |
|-------|--|--------|
| B20DE | Ignition relay OFF circuit (Open circuit or short circuit to ground) | Past   |

**BCM ( 3 DTCs )**

| DTC      | Description                     | Status |
|----------|---------------------------------|--------|
| B25AA:00 | Driver power window actuator    | Past   |
| B25C0:00 | Assist power window actuator    | Past   |
| B25EC:00 | Rear left power window actuator | Past   |

**Technician Notes**

2016994781

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.