Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250513102503
Test Time: 2025-05-13 10:25:03
Technician: Travino

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Sportage(QLE)/--
VIN: U5YPH813MJL530301
Odometer Reading: 150246
License Plate: HS81NJGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.86
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(11)

System	Status/DTC
ENG (Engine)	0
A/T (Transaxle)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	2
CLU (Cluster Module)	0
A/C (Air Conditioner)	0
BCM (Body Control)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
SMK (Smart Key Unit)	0
SJB (Smart Junction Block)	1

DTC (3)

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	History

SJB (Smart Junction Block) (1 DTC)

DTC	Description	Status
B251B:00	Right bi-Function headlamp circuit short to ground	History

Technician Notes

2016875466

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.