



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240918085551
Test Time: 2024-09-18 08:55:51
Technician: Werner

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Navara/--
VIN: VSKCVAD40Z0414249
Odometer Reading: 308662
License Plate: FP25LNGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.90
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine	1
ABS	2
Air bag	1
Meter/M&A	0
BCM	1
HVAC	1
IPDM E/R	0

DTC (6)

Engine (1 DTC)

DTC	Description	Status
P1021	TC boost CONT ACT	1 time

ABS (2 DTCs)

DTC	Description	Status
C1140	Actuator rly	11 time
C1109	Battery voltage	4 time

Air bag (1 DTC)

DTC	Description	Status
B1129	Right side module	CRNT

BCM (1 DTC)

DTC	Description	Status
-----	-------------	--------



U1000 CAN communication circuit

Past

HVAC (1 DTC)

DTC	Description	Status
B2573	Battery voltage OUT OF range	2 time

Technician Notes

2016537084

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.