



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250507132450
Test Time: 2025-05-07 13:24:50
Technician: Andrick

Opel VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Opel/Adam/--
VIN: W0V0MAP08J6053038

Odometer Reading: 100058
License Plate: HR45TFGP

Customer Information

Name: Dekra MFC AUCTION HOUSE









Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine control module	 0
Electronic brake control module	 0
Chassis control module	 0
Inflatable restraint sensing and diagnostic module	 0
Instrument cluster	 0
Power steering control module	 0
Body control module	 1
Radio	 0

DTC (1)

Body control module (1 DTC)

DTC	Description	Status
B3881:04	Tail lamp circuit - Open	DTC history status : History Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Failed MIL status : Not requested

Technician Notes

2016868454



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.