

Opel VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Opel/Corsa-E/--

VIN: W0V0XEP68K4510461

Odometer Reading: 68954

License Plate: JM13NFGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V9.20

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned(9)

System	Status/DTC
Engine control module	1
Electronic brake control module	0
Chassis control module	0
Inflatable restraint sensing and diagnostic module	0
Instrument cluster	0
Power steering control module	0
Parking assist control module	0
Body control module	1
Radio	0

DTC (2)

Engine control module (1 DTC)

DTC	Description	Status
P0011:00	Intake camshaft position system performance	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested

Body control module (1 DTC)

DTC	Description	Status
-----	-------------	--------

C0755:29

Right front tire pressure sensor - Too few pulses

DTC history status :
History
Since DTC clear : Passed
and failed
Last test : Failed current
DTC
This ignition cycle : Failed
MIL status : Not requested

Technician Notes

2016402973

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.