

# Audi VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Audi/Audi A3/S3/RS3>/--  
VIN: WAUZZZ8V1LA035644

Odometer Reading: 124186km  
License Plate: FJH459L

## Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V23.50

Serial Number: VB8GJCC01509  
Repair Order Number: --

 System Scanned ( 15 )

| System                                    | Status/DTC                                                                              |
|-------------------------------------------|-----------------------------------------------------------------------------------------|
| 01 - Engine Control Module 1              |  7   |
| 02 - Transmission electronics             |  5   |
| 03 - Brakes 1                             |  0   |
| 08 - Air Conditioning                     |  1   |
| 09 - Electronic central electric          |  3 |
| 15 - Airbag                               |  0 |
| 17 - Instrument cluster                   |  0 |
| 19 - Gateway                              |  0 |
| 42 - Driver's door electronics            |  0 |
| 44 - Power steering                       |  0 |
| 52 - Passenger's door electronics         |  0 |
| 5F - Information electronics 1            |  0 |
| 76 - Parking aid                          |  0 |
| BB - Rear drivers side door electronics   |  0 |
| BC - Rear passenger side door electronics |  0 |

 DTC ( 16 )

### 01 - Engine Control Module 1 ( 7 DTCs )

| DTC     | Description                                                       | Status           |
|---------|-------------------------------------------------------------------|------------------|
| P190D00 | Coolant pump for charge pressure cooler<br>Mechanical malfunction | Passive/Sporadic |

|         |                                                        |               |
|---------|--------------------------------------------------------|---------------|
| U102600 | Transmission control module<br>Read out DTC            | Active/static |
| P162400 | Requirement - malfunction lamp on<br>active            | Active/static |
| P030000 | Random Misfire Detected<br>No Sub Type Information     | Active/static |
| P030100 | Cylinder 1 Misfire Detected<br>No Sub Type Information | Active/static |
| P030200 | Cylinder 2 Misfire Detected<br>No Sub Type Information | Active/static |
| P030300 | Cylinder 3 Misfire Detected<br>No Sub Type Information | Active/static |

**02 - Transmission electronics ( 5 DTCs )**

| DTC     | Description                     | Status           |
|---------|---------------------------------|------------------|
| P072C00 | Stuck in 1st gear               | Active/static    |
| P073F00 | Unable to Engage Gear 1         | Passive/Sporadic |
| P177D00 | Dual clutch<br>Torque too high  | Passive/Sporadic |
| P189A00 | Clutch 1<br>Clearance too small | Passive/Sporadic |
| P18B900 | Shaft 1<br>Gear shifting failed | Passive/Sporadic |

**08 - Air Conditioning ( 1 DTC )**

| DTC     | Description                                        | Status           |
|---------|----------------------------------------------------|------------------|
| B137A04 | Exterior air quality/air humidity sensor<br>Faulty | Passive/Sporadic |

**09 - Electronic central electric ( 3 DTCs )**

| DTC     | Description                              | Status           |
|---------|------------------------------------------|------------------|
| B147A54 | Remote control key 2<br>No basic setting | Passive/Sporadic |
| B13C429 | Sunroof button<br>Range/performance      | Passive/Sporadic |
| B13C401 | Sunroof button<br>Electrical fault       | Passive/Sporadic |

**Technician Notes**

2017082135

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.