

# Ford VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Ford/Transit/-- Odometer Reading: 83807  
 VIN: WF03XTTG3KL58737 License Plate: JD76CTGP

## Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01482  
 Version: V8.20 Repair Order Number: --

## System Scanned( 9 )

System		Status/DTC
PCM (Powertrain Control Module)		0
ABS (Anti-lock Brake System)		2
RCM (Restraint Control Module)		0
IPC (Instrument Panel Control Module)		0
BCMii (Body Control Module)		0
IPM-B (Image Processing Module B)		0
PAM (Parking Aid Module)		3
SASM (Steering Angle Sensor Module)		0
TRM (Trailer Module)		0

## DTC ( 5 )

### ABS (Anti-lock Brake System) ( 2 DTCs )

DTC	Description	Status
P1708:64-08	Clutch Switch Circuit	CMDTCs
U0422:68-08	Invalid Data Received From Body Control Module	CMDTCs

### PAM (Parking Aid Module) ( 3 DTCs )

DTC	Description	Status
B1B36:14-28	Right Front Outer Sensor	CMDTCs
B1B40:14-28	Left Front Outer Sensor	CMDTCs
B1B42:14-28	Left Front Inner Sensor	CMDTCs

## Technician Notes

2016207074

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*