



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240202112826
Test Time: 2024-02-02 11:28:26
Technician: Andrick

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/Fiesta MY2013/--
VIN: WF0DXXGAKDGR54328

Odometer Reading: 135284
License Plate: FJ36GSGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V8.30

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(12)

System	Status/DTC
PCM (Powertrain Control Module)	 0
ABS (Anti-lock Brake System)	 0
RCM (Restraint Control Module)	 0
IPC (Instrument Panel Control Module)	 0
ACM (Audio Control Module)	 0
APIM (Accessory Protocol Interface Module)	 0
BCMii (Body Control Module)	  1
DDM (Driver Door Module)	 0
FCDIM (Front Control/Display Interface Module)	 1
GPSM (Global Positioning System Module)	 0
PDM (Passenger Door Module)	 0
PSCM (Power Steering Control Module)	 0

DTC (2)

BCMii (Body Control Module) (1 DTC)

DTC	Description	Status
B1108:77-48	Driver door central locking motor	CMDTCs

FCDIM (Front Control/Display Interface Module) (1 DTC)

DTC	Description	Status
B10BD:13-08	Multifunctional Switch	CMDTCs



Technician Notes

2016252626

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.