



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240131105738
Test Time: 2024-01-31 10:57:38
Technician: Sbu

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/Fiesta/--

VIN: WF0JXXGAHJKJ67161

Odometer Reading: 88864km

License Plate: KP86BBGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V8.30

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned(13)

System		Status/DTC
PCM (Powertrain Control Module)		 3
ABS (Anti-lock Brake System)		 1
RCM (Restraint Control Module)		 1
IPC (Instrument Panel Control Module)		 0
ACM (Audio Control Module)		 1
BdyCM(Body control module)		 1
DDM (Driver Door Module)		 0
GWM (Gateway Module A)		 0
HVAC (Heating Ventilation Air Conditioning)		 0
PAM (Parking Aid Module)		 0
PDM (Passenger Door Module)		 1
PSCM (Power Steering Control Module)		 0
SCCM (Steering Column Control Module)		 0

DTC (8)

PCM (Powertrain Control Module) (3 DTCs)

DTC	Description	Status
P0111:00-64	IAT(Intake Air Temperature) Sensor 1 Circuit Range/Performance	CMDTCs
P0113:00-AF	Intake Air Temperature Sensor 1 Circuit High (Bank 1)	CMDTCs



P0217:00-68 Engine Coolant Overtemperature Condition

CMDTCs

ABS (Anti-lock Brake System) (1 DTC)

DTC	Description	Status
U0420:86-68	Invalid Data Received from Power Steering Control Module A	CMDTCs

RCM (Restraint Control Module) (1 DTC)

DTC	Description	Status
B1404:13-08	Driver Side Airbag Deployment Control	CMDTCs

ACM (Audio Control Module) (1 DTC)

DTC	Description	Status
U2013:01-28	Switch Pack	CMDTCs

BdyCM(Body control module) (1 DTC)

DTC	Description	Status
B121A:11-48	Keypad Illumination Output	CMDTCs

PDM (Passenger Door Module) (1 DTC)

DTC	Description	Status
B118A:3A-28	Rear Window Position Sensor	CMDTCs

Technician Notes

2016249247

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.