



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	02/09/2025		M57 Pretoria Road - 1619
Inspection Date	02/09/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	KIA	Registration Number	KD72PSGP
Model	PEGAS	Register Number	
VIN	LJD0AA29LN0159232	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/08/2023
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	99,170 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: LJD0AA29LN0159232



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025

	Damage	Repair Way
	Tail Light Left Damaged Tail Light Right Damaged Front Bumper Damaged Bonnet Damaged C • Pillar Left Damaged C • Pillar Right Damaged Front Fender Left Damaged Front Fender Right Damaged Rear Fender Left Damaged Rear Fender Right Damaged Door Front Left Damaged Door Front Right Damaged Door Rear Left Damaged Door Rear Right Damaged Boot Lid / Hatch door Damaged Rear bumper Damaged Roof Damaged Tyre Front Left Worn Tyre Front Right Worn Tyre Rear Left Worn Tyre Rear Right Worn	Replace Replace Repair Repair Repair Repair Repair Repair Repair Repair Repair Repair Repair Repair Repair Repair Replace Replace Replace Replace

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.24	1.97	-	
Rear	2.14	2.21	-	
Emergency / Parking	1.3	1.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82V	Symmetry	Radial	V	1224	0 mm
Front Right	175/70R14	84T	Nexen	Radial	V	2221	0 mm
Rear Left	175/70R14	84T	Autogrip	Radial	V	3216	0 mm
Rear Right	175/70R14	84T	Tracmax	Radial	V	4922	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LJD0AA29LN0159232



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	BCM	B1214:00	LEFT REAR SENSOR FAULT	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. Vehicle body in poor condition. Signs of hail damage to some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: LJD0AA29LN0159232




CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025



Brake test.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LJD0AA29LN0159232



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LJD0AA29LN0159232



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LJD0AA29LN0159232



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LJD0AA29LN0159232



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LJD0AA29LN0159232



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025



C • Pillar Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Rear Fender Right



C • Pillar Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LJD0AA29LN0159232



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025



Front Fender Right



Door Front Right



Door Rear Right



Roof



Tail Light Left



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LJD0AA29LN0159232



CONDITION REPORT



Report No:
2016999204
DATE
02/09/2025



Tyre Rear Left



Tyre Rear Right



Tyre Front Left



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LJD0AA29LN0159232