



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	27/05/2024		M57 Pretoria Road - 1619
Inspection Date	27/05/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	FORD	Registration Number	NU92900
Model	FIGO	Register Number	
VIN	MAJFXXMTKFKC57754	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	27/05/2024
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	109,501 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Headlight Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Rear Left Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Tyre Rear Right Worn	Replace
Gearbox Mountings Worn	Replace
Body and exterior	Signs of repair work done to somebody panels.
Body and exterior	Poor alignment to somebody panels.
Body and exterior	Repair work done to vehicle below standard.
Body and exterior	Vehicle body in poor condition.
Body and exterior	Signs of impact damage to front of vehicle.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFKC57754

1 / 9



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.47	2.12	-	
Rear	1.5	1.68	-	
Emergency / Parking	1.2	1.54	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Road king	Radial	V	3123	3 mm
Front Right	175/65R14	82H	Road king	Radial	V	3123	3 mm
Rear Left	175/65R14	82T	Sava	Radial	V	3621	3 mm
Rear Right	175/65R14	82H	Apollo	Radial	V	5118	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT


VIN: MAJEXYM5KFKG57764

Report No: 2016395043


2 / 9

DATE


27/05/2024



Brake and shock test



Diagnostic report



Diagnostics.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016395043
VIN: MAJFXXMTKFKC57754
DATE
3/15
27/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395043

DATE
VIN: MAJFXXMTKFKC5775
27/05/2024
4/9



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



CONDITION REPORT

Report No: 2016395043

DATE

27/05/2024

VIN: MAJFXXMTKFKC57754

5 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

VIN: MAJFXXMTKFKC57754

6 / 9



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

VIN: MAJFXXMTKFKC57754
7 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

VIN PLATE OR STICKER



ENGINE 1

VIN: MAJFXXMTKFKC57754

8 / 9



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

VIN: MAJFXXMTKFKC57754

9 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

Bonnet slam plate (Shock tower/ Inner tray)



Headlight Right




Front Bumper



Front Bumper



Bonnet



Front Fender Left



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

Door Front Left



Door Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Rear Fender Left



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

Front Fender Right



Rear Fender Right



Tyre Rear Right



Gearbox Mountings



CONDITION REPORT

Report No: 2016395043

DATE
27/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za