

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	20/06/2024		M57 Pretoria Road - 1619
Inspection Date	20/06/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	NISSAN	Registration Number	JL49VRGP
Model	ALMERA	Register Number	
VIN	MDHBBAN17Z0728909	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/11/2024
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	67,774 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Wiring Defective	Repair
Air conditioner pump Damaged	Replace
Air conditioner pipes Damaged	Repair
Air cleaner Damaged	Replace
Headlight Left Cracked	Replace
Interior Mirror Missing	Replace
Door Hinges Rear Left Damaged	Replace
Dash Padding Excessive Wear & Tear	Replace
Carpet Rear Torn / Cut	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Residual Traces of Repair	Repair
Rear Lower Valance Damaged	Repair
Bonnet Residual Traces of Repair	Repair
A • Pillar Left Residual Traces of Repair	Repair
A • Pillar Right Residual Traces of Repair	Repair
B • Pillar Left Damaged	Repair
C • Pillar Left Dented	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Sill Panel Left Residual Traces of Repair	Repair
Roof Residual Traces of Repair	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0728909

1 / 21

Damage	Repair Way
Windscreen Cracked	Replace
Brake Piping Damaged	Replace
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Steering Rack Boot Left Torn / Cut	Replace
Steering Rack Boot Right Torn / Cut	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Damaged	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Tyre Rear Right Smooth	Replace
Main Beam Left Welded	Replace
Main Beam Right Damaged	Replace
Sub Frame Damaged	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Engine Performance Insufficient	Repair
Electronics malfunction.	Hooter not working
See additional 9 coolant reservoir missing	Replace.
Body exterior	Signs of spray work done on all body panels
Warning lights illuminated	Repair.
Vehicle structural integrity compromised.	Vehicle is unsafe to drive
Vehicle is a cut and join.	Replace.

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.6	2.3	-	
Rear	0.0	0.0	-	
Emergency / Parking	1.3	1.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Symmetry	SY300	V	0520	2 mm
Front Right	185/65R15	88H	Symmetry	SY300	V	0000	2 mm
Rear Left	185/65R15	88H	Timax	Eco comfort	V	2521	2 mm
Rear Right	185/65R15	88H	Timax	Eco comfort	V	2521	0 mm
Spare	185/65R15	88H	Bridgestone	B250	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. RESIDUAL TRACES OF POOR REPAIR WORK DONE ON ALL BODY PANELS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician




DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



4/37

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0728909
6 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0728909

7 / 21



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0728909
8 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

VIN: MDHBBAN17Z0728909
10 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



R/F fender liner missing



Rear end

VIN: MJB8BAN17Z0728909

11 / 21



Warning lights illuminated



ABS warning lights illuminated



Oil cap and dipstick



Coolant reservoir missing

VIN: MDHBBAN17Z0728909
12 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Floor pan cut



Floor pan cut

VIN: MD8BBAN17Z0728909

13 / 21



Floor pan cut.



Interior Mirror



Steering Wheel Trim



Dash Padding

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0728909

14 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Carpet Rear



Boot Lid / Hatch door

VIN: MDHBBAN17Z0728909

15 / 21



Rear Fender Left



Door Rear Left



A • Pillar Left



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0728909
16 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Roof



Roof

VIN: MDHBBAN17Z0728909

17 / 21



Door Front Left



Side Mirror Left



Front Fender Left



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0728909
18 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Windscreen



Headlight Left



Door Hinges Rear Left



B • Pillar Left



C • Pillar Left



Door Front Left

VIN: MDHBBAN17Z0728909

19 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0728909
20 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



B • Pillar Left

Shock absorber test (MSD3000)				
	left	right	Difference	Weight
Front axle	> 0,30	> 0,30	0 %	610 kg
Rear axle	0,28	0,24	14 %	436 kg
Total weight				610 kg

Brake Test				
	left	right	Difference	
Front axle	2,61 kN	2,39 kN	9 %	
Parking brake	1,30 kN	1,65 kN	21 %	
Rear axle	— kN	— kN	— %	
Final evaluation static				
Deceleration service brake		84 %		
Deceleration parking brake		49 %		Total weight

Service Brake Performance Rear Axle



Air conditioner pipes



Air conditioner pipes



Air conditioner pipes



Air conditioner pump

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Main Beam Right



Engine Wiring



Engine Wiring



Engine Wiring



Engine Wiring



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Air cleaner



A • Pillar Right



A • Pillar Right



Front Fender Right



Door Front Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Rear Fender Right



Sub Frame



Main Beam Right



CV Joint(s) Boot(s) Front Left (inner/outer)



Stabilizer Mounting Front Left



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Main Beam Left



Rear bumper



Rear bumper



Rear bumper



Tyre Rear Right



Bolt(s) / Nut(s) Rear Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Stabilizer Mounting Front Right



Steering Rack Boot Right



Steering Rack Boot Left



CV Joint(s) Boot(s) Front Left (inner/outer)



Sill Panel Left



Rear Lower Valance

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Rear Lower Valance



Rear Lower Valance



Rear Lower Valance



Rear Lower Valance



Brake Piping



Brake Piping

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Brake Piping

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za