



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/08/2025		M57 Pretoria Road - 1619
Inspection Date	28/08/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	NISSAN	Registration Number	KHP213NW
Model	QASHQAI 1.2 T VISIA + ALLOYS 5-DR [2018-2020]	Register Number	
VIN	SJNFEAJ11Z2688108	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	BLUE	Power / Displacement	
Year Model	2019	Paint Finish	TWO COAT UNI
Km Reading	119,908 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



Damage	Repair Way
Engine Oil Sweat	Repair
Radio/CD/USB Defective	Repair
Windscreen Wiper Damaged	Replace
Tail Light Left Cracked	Replace
Headlight Left Damaged	Replace
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Rear Fender Left Dented	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Dented	Smart Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Dented	Repair
Windscreen Damaged	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Torn / Cut	Replace
Chassis Dented	Repair
Belly plates Damaged	Repair
Jack Missing	Replace
Warning lights illuminated on dashboard	Repair
Body and Exterior	Poor residual traces of repair on some body panels
Body and Exterior	Some body panels misaligned
Body and Exterior	Spray work on some body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.03	3.01	-	
Rear	2.5	2.45	-	
Emergency / Parking	1.4	1.43	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60 R17	96H	Hilo	Sport	V	0124	2 mm
Front Right	215/60 R17	96H	Hilo	Sport	V	0124	1 mm
Rear Left	215/60 R17	100V	Aceelera	Radial	V	3324	4 mm
Rear Right	215/60 R17	100H	Radar	RPX-800	V	0924	5 mm
Spare	215/65 R16	98H	Bridgestone	Dueler	V	2619	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	U0121:87	LOST COMMUNICATION(ABS)	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Engine bay dirty. Foreign substance in expansion bottle.

Interior: Vehicle interior dirty and some panels scratched

Undercarriage: Bottom of engine and gearbox fully covered. Vehicle undercarriage dirty

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE LEFT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)




INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



RF TYRE TREAD



LF TYRE TREAD



Spare wheel and Accessories



Oil cap and dipstick



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025




ENGINE 1




VIN PLATE OR STICKER




LICENSE DISC



SHOCK AND BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: SJNFEAJ11Z2688108




CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



DIAGNOSTIC REPORT PAGE 3




Seat Front Right



Windscreen



Windscreen Wiper



Bonnet



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



Door Front Right



Door Rear Right



Door Front Right



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



Tail Light Left



Rear Fender Left



Door Rear Left



Door Front Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



Front Bumper



Front Bumper



Front Bumper



Headlight Left



Control Arm Bush(es) Front Axle Right



Rear Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



Sill Panel Right



Chassis



Chassis



Belly plates



Tyre Front Left



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108



CONDITION REPORT



Report No:
2016994781
DATE
28/08/2025



Engine



Radio/CD/USB

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z2688108