



CONDITION REPORT

Report No: 2016883076

DATE  
19/05/2025

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	20/05/2025		M57 Pretoria Road - 1619
Inspection Date	19/05/2025		Kempton Park - GT

Vehicle Data


Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	AUDI	Registration Number	LS87DDGP
Model	S3 SEDAN 213KW QUATTRO S TRONIC [2022-2024]	Register Number	
VIN	WAUZZZGY0PA029108	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/04/2025
Color	YELLOW	Power / Displacement	
Year Model	2023	Paint Finish	C - COMMON
Km Reading	58,525 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Front Bumper Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Tyre Front Left Damaged	Repair
Body exterior	Vehicle got minor scratches, stone chips and dents
Brakes	No brake test done vehicle is 4wd



DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WAUZZZGY0PA029108



## CONDITION REPORT

Report No: 2016883076

 DATE  
19/05/2025

### Brakes

#### Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

### Tyres and Rims

#### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	235/35R19	91Y	Apollo	Aspire	V	1323	4 mm
Front Right	235/35R19	91Y	Apollo	Aspire	V	2923	4 mm
Rear Left	235/35R19	91Y	Apollo	Aspire	V	1323	4 mm
Rear Right	235/35R19	91Y	Apollo	Aspire	V	2923	4 mm
Spare	T125/70R18	99M	Ling long	Temporary	V	0000	2 mm

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ACTIVE/ STATIC	B101C07	DRIVER SEAT BELT SWITCH MECHANICAL FAULT	

### Inspection Conditions

No Test Drive  
 Battery Flat  
 Engine number – not possible to verify engine number (not visible without dismantling)  
 Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
 www.dekraauto.co.za

VIN: WAUZZZGY0PA029108




## CONDITION REPORT

Report No: 2016883076

DATE  
19/05/2025

Shock report



Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER


DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WAUZZZGY0PA029108



## CONDITION REPORT

Report No: 2016883076

DATE  
19/05/2025

REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WAUZZZGY0PA029108





## CONDITION REPORT

Report No: 2016883076

DATE  
19/05/2025


90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: WAUZZZGY0PA029108



## CONDITION REPORT

Report No: 2016883076

DATE  
19/05/2025

RF TYRE TREAD



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WAUZZZGY0PA029108





## CONDITION REPORT

Report No: 2016883076

DATE  
19/05/2025

CHASSIS



Expansion bottle



Oil cap and dipstick



Water level



Rear Fender Right



Door Front Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WAUZZZGY0PA029108



## CONDITION REPORT

Report No: 2016883076

DATE  
19/05/2025

Front Fender Right



Front Bumper



Rear Fender Left



Tyre Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WAUZZZGY0PA029108