



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	12/08/2025		M57 Pretoria Road - 1619
Inspection Date	12/08/2025		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	MERCEDES-BENZ	Registration Number	FF24DZGP
Model	CLA 200	Register Number	
VIN	WDD1173032N343198	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	
Color	GREY	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	221,509 KM	Fuel	DIESEL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WDD1173032N343198



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025



Damage	Repair Way
Wiper Switch Damaged	Replace
Center Console / Cubbyhole + Lid Defective	Repair
Tail Light Right Broken	Replace
Headlight Left Damaged	Replace
Seat Front Right Damaged	Repair
Mirror Adjusters Malfunction	Replace
Number Plate Rear Missing	Replace
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet Paintwork • Scratched	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Rocker Panel Left Damaged	Replace
Windscreen Chipped	Repair
Brake Piping Defective	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Worn	Replace
Rim Front Left Dented	Repair
Rim Front Right Scratched	Repair
Rim Rear Right Scratched	Repair
Belly plates Damaged	Replace
Radiator Cradle Damaged	Repair
Engine Noise Excessive	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Warning lights illuminated on dashboard	Repair
Body and Exterior	Front emblem missing
Interior	Bonnet release handle missing
Tyres and rims	Spare wheel missing
Undercarriage	Bottom of engine and gearbox fully covered
Body and Exterior	Poor residual traces of repair on some body panels
Body and Exterior	Stone chips and spray work on some body panels
Body and Exterior	Dents and scratches on some body panels
Interior	Some electrical instruments faded
Road test	Power Steering insufficient
Undercarriage	Front left and rear left jacking points missing
Tyres and rims	Front right and rear right center caps missing
Tyres and rims	Front and rear tyre sizes different
Axle and suspension	Front suspension noisy
Body and Exterior	Some body panels misaligned

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:

2016976204

DATE

12/08/2025

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.36	3.82	-	
Rear	2.57	2.57	-	
Emergency / Parking	0.95	0.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40 R18	92W	Continental	Contisport	V	1722	2 mm
Front Right	215/40Z R18	89W	Fronway	Eurus 08	V	1923	1 mm
Rear Left	235/50 R18	97W	Pirelli	Cinturato	V	0715	2 mm
Rear Right	225/50 R18	95W	Pirelli	Cinturato	V	4717	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM(ENGINE CONTROL UNIT)	P056013	THE ON-BOARD ELECTRICAL SYSTEM VOLTAGE HAS A MALFU	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025

[illegible]

Brake and shock absorber report



Volkswagen
 Volkswagen Group of America
 Volkswagen of America, Inc.
 100 West 26th Street
 New York, NY 10001-2298
 Tel: 212 859 2000
 Fax: 212 859 2001
 E-Mail: usa@volkswagen.com
 Web: www.volkswagen.com

電話 02-2626-1111
傳真 02-2626-1112
傳呼 02-2626-1113
傳真 02-2626-1114
傳呼 02-2626-1115
傳呼 02-2626-1116
傳呼 02-2626-1117
傳呼 02-2626-1118
傳呼 02-2626-1119
傳呼 02-2626-1120
傳呼 02-2626-1121
傳呼 02-2626-1122
傳呼 02-2626-1123
傳呼 02-2626-1124
傳呼 02-2626-1125
傳呼 02-2626-1126
傳呼 02-2626-1127
傳呼 02-2626-1128
傳呼 02-2626-1129
傳呼 02-2626-1130
傳呼 02-2626-1131
傳呼 02-2626-1132
傳呼 02-2626-1133
傳呼 02-2626-1134
傳呼 02-2626-1135
傳呼 02-2626-1136
傳呼 02-2626-1137
傳呼 02-2626-1138
傳呼 02-2626-1139
傳呼 02-2626-1140
傳呼 02-2626-1141
傳呼 02-2626-1142
傳呼 02-2626-1143
傳呼 02-2626-1144
傳呼 02-2626-1145
傳呼 02-2626-1146
傳呼 02-2626-1147
傳呼 02-2626-1148
傳呼 02-2626-1149
傳呼 02-2626-1150
傳呼 02-2626-1151
傳呼 02-2626-1152
傳呼 02-2626-1153
傳呼 02-2626-1154
傳呼 02-2626-1155
傳呼 02-2626-1156
傳呼 02-2626-1157
傳呼 02-2626-1158
傳呼 02-2626-1159
傳呼 02-2626-1160
傳呼 02-2626-1161
傳呼 02-2626-1162
傳呼 02-2626-1163
傳呼 02-2626-1164
傳呼 02-2626-1165
傳呼 02-2626-1166
傳呼 02-2626-1167
傳呼 02-2626-1168
傳呼 02-2626-1169
傳呼 02-2626-1170
傳呼 02-2626-1171
傳呼 02-2626-1172
傳呼 02-2626-1173
傳呼 02-2626-1174
傳呼 02-2626-1175
傳呼 02-2626-1176
傳呼 02-2626-1177
傳呼 02-2626-1178
傳呼 02-2626-1179
傳呼 02-2626-1180
傳呼 02-2626-1181
傳呼 02-2626-1182
傳呼 02-2626-1183
傳呼 02-2626-1184
傳呼 02-2626-1185
傳呼 02-2626-1186
傳呼 02-2626-1187
傳呼 02-2626-1188
傳呼 02-2626-1189
傳呼 02-2626-1190
傳呼 02-2626-1191
傳呼 02-2626-1192
傳呼 02-2626-1193
傳呼 02-2626-1194
傳呼 02-2626-1195
傳呼 02-2626-1196
傳呼 02-2626-1197
傳呼 02-2626-1198
傳呼 02-2626-1199
傳呼 02-2626-1200
傳呼 02-2626-1201
傳呼 02-2626-1202
傳呼 02-2626-1203
傳呼 02-2626-1204
傳呼 02-2626-1205
傳呼 02-2626-1206
傳呼 02-2626-1207
傳呼 02-2626-1208
傳呼 02-2626-1209
傳呼 02-2626-1210
傳呼 02-2626-1211
傳呼 02-2626-1212
傳呼 02-2626-1213
傳呼 02-2626-1214
傳呼 02-2626-1215
傳呼 02-2626-1216
傳呼 02-2626-1217
傳呼 02-2626-1218
傳呼 02-2626-1219
傳呼 02-2626-1220
傳呼 02-2626-1221
傳呼 02-2626-1222
傳呼 02-2626-1223
傳呼 02-2626-1224
傳呼 02-2626-1225
傳呼 02-2626-1226
傳呼 02-2626-1227
傳呼 02-2626-1228
傳呼 02-2626-1229
傳呼 02-2626-1230
傳呼 02-2626-1231
傳呼 02-2626-1232
傳呼 02-2626-1233
傳呼 02-2626-1234
傳呼 02-2626-1235
傳呼 02-2626-1236
傳呼 02-2626-1237
傳呼 02-2626-1238
傳呼 02-2626-1239
傳呼 02-2626-1240
傳呼 02-2626-1241
傳呼 02-2626-1242
傳呼 02-2626-1243
傳呼 02-2626-1244
傳呼 02-2626-1245
傳呼 02-2626-1246
傳呼 02-2626-1247
傳呼 02-2626-1248
傳呼 02-2626-1249
傳呼 02-2626-1250
傳呼 02-2626-1251
傳呼 02-2626-1252
傳呼 02-2626-1253
傳呼 02-2626-1254
傳呼 02-2626-1255
傳呼 02-2626-1256
傳呼 02-2626-1257
傳呼 02-2626-1258
傳呼 02-2626-1259
傳呼 02-2626-1260
傳呼 02-2626-1261
傳呼 02-2626-1262
傳呼 02-2626-1263
傳呼 02-2626-1264
傳呼 02-2626-1265
傳呼 02-2626-1266
傳呼 02-2626-1267
傳呼 02-2626-1268
傳呼 02-2626-1269
傳呼 02-2626-1270
傳呼 02-2626-1271
傳呼 02-2626-1272
傳呼 02-2626-1273
傳呼 02-2626-1274
傳呼 02-2626-1275
傳呼 02-2626-1276
傳呼 02-2626-1277
傳呼 02-2626-1278
傳

Diagnostic report page 1

[illegible]

Diagnostic report page 2

[illegible]

Diagnostic report page 3

[illegible]

Diagnostic report page 4

[illegible]

Diagnostic report page 5

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:


2016976204

DATE

12/08/2025



Diagnostic report page 6



Diagnostic report page 7



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:

2016976204

DATE

12/08/2025



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198




CONDITION REPORT




Report No:
2016976204
DATE
12/08/2025



LF TYRE TREAD



LR TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



Triangle



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WDD1173032N343198



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025



Seat Front Right



Front Fender Right



Door Front Right



Door Rear Right



Rear Fender Right



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025



Rear bumper



Boot Lid / Hatch door



Rear Fender Left



Door Rear Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025



Windscreen



Front Bumper



Front Bumper



Bonnet



Grill



Headlight Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198




CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025



Tail Light Right



Parking Brake Performance



Rim Front Right



Rim Front Left



Tyre Front Left



Rocker Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198




CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025



Tyre Rear Left




Rim Rear Right



Belly plates



Belly plates



Tyre Front Right



Stabilizer Mounting Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025



Brake Piping




Radiator Cradle



Radiator Cradle



Stabilizer Mounting Front Right



Tyre Rear Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198



CONDITION REPORT



Report No:
2016976204
DATE
12/08/2025



Wiper Switch



Mirror Adjusters



Number Plate Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD1173032N343198