



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	13/03/2024		M57 Pretoria Road - 1619
Inspection Date	13/03/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	FORD	Registration Number	HZ90JVGP
Model	FOCUS	Register Number	
VIN	WF04XXGCC4HC78289	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/07/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	218,155 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Sweat	Repair
Expansion Bottle Defective	Replace
Battery box Corrosion	Repair
Battery clamps Corrosion	Repair
Head Light Switch Defective	Repair
Switch Electrical Window Winder front left Malfunction	Replace
Tail Light Right Scratched	Repair
Seat Front Right Damaged	Repair
Seat Belt Rear Middle Damaged	Replace
Hood Lining Dirty	Repair
Steering Wheel Trim Defective	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Sill Panel Left Dented	Repair
Windscreen Chipped	Repair
Stabilizer Mounting Front Left Defective	Replace
Stabilizer Mounting Front Right Defective	Replace
Tyre Front Left Defective	Replace
Rim Front Left Scratched	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4HC78289

1 / 15



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

Damage	Repair Way
Rim Front Right Scratched	Repair
Rim Rear Left Dented	Repair
Rim Rear Right Scratched	Repair
Chassis Dented	Repair
Sub Frame Scratched	Repair
Silencer Defective	Repair
Catalytic converter Defective	Repair
Engine mountings Cracked	Replace
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
Undercarriage	Bottom of engine and gearbox fully covered.
Engine	Engine bay dirty
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Poor residual traces of repair on some body panels
Body and Exterior	Some body panels misaligned
Body and Exterior	Stone chips and Spray work on some body panels
Axle and suspension	Front and rear suspension noisy

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.13	3.13	-	
Rear	1.88	1.77	-	
Emergency / Parking	1.45	1.34	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55Z R16	94W	Xcent	EL601	V	4621	3 mm
Front Right	205/55Z R16	94W	Xcent	EL601	V	4621	4 mm
Rear Left	205/55Z R16	94W	Xcent	EL601	V	4621	4 mm
Rear Right	205/55Z R16	94W	Xcent	EL601	V	4621	4 mm
Spare	T125/70 R16	96M	Hankook	Temporary	V	2417	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM(POWERTRAIN CONTROL MODULE)	P0096:00-64	IAT(INTAKE AIR TEMPERATURE) SENSOR 2 CIRCUIT RANGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

**CONDITION REPORT**

VIN: W504XYG004630462

Report No: 201630462

2 / 15

DATE**13/03/2024**

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462


VIN: WF04XXGCC4HC78289

DATE
13/03/2024

Brake and shock absorber report



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016304462

VIN: WF04XXGCGJH010024
DATE: 13/03/2024
4 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

VIN: WF04XXGCC4HC78289

5 / 15



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

VIN: WF04XXGCC4HC78289
6 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

90 DEGREE LEFT



LF TYRE TREAD

C4HC78289
7 / 15

LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

VIN: WF04XXGCC4HC78289

8 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Rear chassis



Front chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

VIN: WF04XXGCC4HC78289

10 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

Head Light Switch



Steering Wheel Trim

VIN: WF04XXGCC4HC78289

11 / 15



Hood Lining



Seat Front Right



Seat Belt Rear Middle



Switch Electrical Window Winder front left



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

VIN: WF04XXGCC4HC78289
12 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

Sill Panel Left



Windscreen



Front Bumper



Front Bumper



Bonnet



Expansion Bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

VIN: WF04XXGCC4HC78289

14 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

Rear bumper



Rear bumper

C4HC78289
15 / 15

Seat Belt Rear Middle



Tail Light Right



Side Mirror Right



Front Fender Right / Inner Tray



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

Rim Front Right



Door Front Right



Door Rear Right



Rear Fender Right



Rim Rear Right



Rim Rear Left



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

Rear Fender Left



Door Rear Left



Door Front Left



Front Fender Left



Rim Front Left



Belly plates



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

Belly plates



Tyre Front Left



Sub Frame



Chassis



Silencer



Belly plates



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

Chassis



Rim Rear Left



Chassis



Stabilizer Mounting Front Left



Gearbox



Engine



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016304462

DATE
13/03/2024

Stabilizer Mounting Front Right



Water level



Engine mountings



Battery clamps



Battery box



Catalytic converter

**CONDITION REPORT****Report No: 2016304462****DATE**
13/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za